


TO FURTHER PHONES
AND CD204 AS REQ.



NOTE:
THIS DRAWING INDICATES AND ASSUMES THE USE OF
BPT COMPOSITE CABLES OR A SUITABLE EQUIVALENT.

ENSURE ALL ADDITIONAL CONNECTIONS ARE
A MINIMUM OF 0.5MM CSA PARALLEL CONDUCTORS.


INCORRECT CABLE SPEC CAN CAUSE DIGITAL
SIGNALING PROBLEMS.

NOTE: CABLE EQUIVALENTS

VCM/130 = RG59 COAX + 4 CORES @ 1.0MMSQ + 8 CORES @ 0.5MMSQ

VIDEO SIGNAL TO RF MODULATOR (BY OTHERS).
NOTE SIGNAL ONLY PRESENT WHEN THIS SYSTEM
IS ACTIVE, I.E... CAMERA CAN NOT BE
PERMANENTLY ON.

3 CORES @ 0.5MMSQ +
2 CORES @ 1.0MMSQ.



BPT (UK) LTD. HERTS. ENGLAND	PREPARED FOR INSTALLER INFORMATION	DATE: 06/04/04	DRAWN:RC
		REVISED:	
DRAWING TITLE:	2 X DIGITAL TARGHA VIDEO ENTRY PANELS & LYNEA AUDIO HANDSETS WITH VIDEO TO RF MODULATOR	DRAWING No: B-XT2YNC(AUD)	